

WORK PERMIT # ____

Work Order #	Job #	Activity #		
1. Work requester fills out	this section	STANDING WORK PERMIT		
Work Control Coordinator	rent from requester):	Start Date 10/10/01 Est. End Date 10/12/01 TD Shielding Maide		
Building /1008 Room	m Equipment	Service Provider		
2. Work requester, service provider, and ES&H (as necessary) fill out this section or attach analysis ES&H Analysis RADIATION CONCERNS [] NONE [] Special nuclear materials involved, notify Isotope Special Materials Group [] Fissionable materials involved, notify Laboratory Criticality Officer SAFETY CONCERNS [] NONE [] Adding / Removing [] Confined Space* [] Explosives [] Lead* [] Penetrating Fire Wall				
Walls or Roofs [] Co [] Asbestos* [] Cry [] Beryllium* ★ Ele [] Biohazard* [] Ele [] Chemicals* [] Exc	rosive [] Flammable rogenic [] Fumes/Mist/Dust* ctrical [] Heat/Cold Stress* vated Work* [] Hydraulic cavation [] Lasers*	[] Lead* [] Magnetic Field (8 gures) [] Penetrating Fire Wall [] Material Handling [] Pressurized Systems [] Rigging/Critical Lift [] Non-ionizing Radiation [] Oxygen Deficiency* [] OTHER		
ENVIRONMENTAL CONCERNS NONE				
	ASTE MINIMIZATION OPPORTUNITY	Y: [] None [] Yes		
POLLUTION PREVENTION (P2) / WASTE MINIMIZATION OPPORTUNITY: [] None [] Yes Facility Concerns [] Access/Egress Limitations [] Impacts Facility Use Agreement [] Temperature Change [] OTHER				
Work Controls WORK [NONE PRACTICES [] Back-up Perso [] Barricades	n/Watch [] HP Coverage [] Lockout/Tagout [] Spill Containment] Posting/Warning Signs [] Time Limitation] Scaffolding - requires inspection [] Warning alarm (i.e. "high level")		
PROTECTIVE [] NONE EQUIPMENT [] Coveralls [] Disposable Cle	[] Ear Plugs [] Gloves [] Ear Muffs [] Goggles othing [] Face Shield [] Hard Hat	[] Lab Coat [] Safety Glasses [] Respirator [] Safety Harness [] Shoe covers [] OTHER		
PERMITS Initial next to box REQUIRED [NONE] (Please attach) [Concrete/Mass [Confined Space]	[] Cutting/Welding onry Penetration [] Digging/Core Dri	illing [] Rad Work Permit - RWP No		
DOSIMETRY/ MONITORING [] Air Effluent [] Ground Water [] Liquid Effluen	[] Noise Survey/Dosimeter [] O ₂ /Combustible Gas [Real Time Monitor		
Training Requirements (List below any location specific training requirements) C-A Access, Cscont Policy				
Based on analysis above, the Walkdon ES&H Risk Level: Complexity Level:		Note: If all the ratings are LOW, the Work Control Coordinator		
Work Coordination: ∠LOV		and Service Provider must sign for concurrence on the back side. Further review of the work permit is not required. If any ratings are MODERATE or HIGH, the entire permit must be completed.		

FILE CODE:

BNL F3093A

work Plan: (procedures, tim	V 32 32 32	120 To 1 To	the same of the sa
<i>Sce</i>	ning, equipment, and personnel a	availability need to be addre	ssed)
<i>See</i>	Attached		
Special Working Conditions I	Required: Non C		
Operational Limits Imposed:			
Post Work Testing Required:		VVV II 1	
Job Safety Analysis Required			Yes _XNo
be controlled according to BNL:	er signature means that the hazard requirements.	s and risks that could impact E	ures required based on hazards and S&H have been identified and will
Title	Name (print)	Signature	Life # Date
Primary Reviewer ES&H Professional	Y. Makdisi Uf	Markes	1553) 10/9/01
Other	P. KROON	Peter Kan	1200 (3/6/2)
Other C. Per KSON	A. Pondaci	De Fo	N CP 17501 10/9/01
Work Control Coordinator*	P. KROOH	Oth I wan	17500 13/9/01
Service Provider*		THE PLANT OF THE PARTY OF THE P	1 1300 1017101
*Only signatures required for co	oncurrence on I OW rated jobs		David and the second
4. Job site personnel fills o	THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO I		Review done: in series team
	performing work have read and unders	stand the horande and a site	
Job Site Supervisor 500	Attached	Contractor Supervisor	rements (including attached permits).
Workers:	Life #		T : C- #
	Elic#	Workers:	Life #
DEC HTTQU			
See Attack			
-	feedback on ES&H concerns or on idea.	s for improved job work flow. Use	e feedback form or space below.
-	feedback on ES&H concerns or on idea.	s for improved job work flow. Use	e feedback form or space below.
Workers are encouraged to provide f 5. Work Requester or desig Conditions are Appropriate	feedback on ES&H concerns or on idea. Thee fills out this section		
Workers are encouraged to provide for the State of the St	feedback on ES&H concerns or on ideal three fills out this section to Start Work: (Work permit has b		ce, and site is ready for job.)
Workers are encouraged to provide for the state of the st	feedback on ES&H concerns or on ideal three fills out this section to Start Work: (Work permit has b	een reviewed, work controls are in pla Life	ce, and site is ready for job.)
Workers are encouraged to provide for the state of the st	feedback on ES&H concerns or on ideal gnee fills out this section to Start Work: (Work permit has b Signature	een reviewed, work controls are in pla Life uiredNoYes	ce, and site is ready for job.) # <u>17500</u> Date <u>10/10/01</u> s (Fill in names of reviewers)
Workers are encouraged to provide for the state of the st	feedback on ES&H concerns or on ideal the fills out this section to Start Work: (Work permit has be Signature	een reviewed, work controls are in pla Life uiredNoYes Life #:	ce, and site is ready for job.) # <u>17500</u> Date <u>10/10/01</u> S (Fill in names of reviewers) Date:
Workers are encouraged to provide for the state of the st	feedback on ES&H concerns or on idea. Inee fills out this section to Start Work: (Work permit has be Signature	een reviewed, work controls are in pla Life uiredNoYes Life #:	ce, and site is ready for job.) # <u>17500</u> Date <u>10/10/01</u> S (Fill in names of reviewers) Date:
Workers are encouraged to provide for the following of the following seems of the following	feedback on ES&H concerns or on ideal time fills out this section to Start Work: (Work permit has by Signature	een reviewed, work controls are in pla Life uiredNoYes Life #:	ce, and site is ready for job.) # <u>17500</u> Date <u>10/10/01</u> S (Fill in names of reviewers) Date:
Workers are encouraged to provide f 5. Work Requester or desig Conditions are Appropriate Name P. KROON 6. Work Requester determine Post Job Review: Name: Name: Name: 7. Worker provides feedbace	feedback on ES&H concerns or on ideal time fills out this section to Start Work: (Work permit has by Signature	een reviewed, work controls are in pla Life uiredNoYes Life #:	ce, and site is ready for job.) # <u>17500</u> Date <u>10/10/01</u> S (Fill in names of reviewers) Date:
Workers are encouraged to provide for the following of the following seems of the following	feedback on ES&H concerns or on ideal time fills out this section to Start Work: (Work permit has by Signature	een reviewed, work controls are in pla Life uiredNoYes Life #:	ce, and site is ready for job.) # <u>17500</u> Date <u>10/10/01</u> S (Fill in names of reviewers) Date:
Workers are encouraged to provide f 5. Work Requester or desig Conditions are Appropriate Name P. KROON 6. Work Requester determine Post Job Review: Name: Name: Name: 7. Worker provides feedbace	feedback on ES&H concerns or on ideal time fills out this section to Start Work: (Work permit has by Signature	een reviewed, work controls are in pla Life uiredNoYes Life #:	ce, and site is ready for job.) # <u>17500</u> Date <u>10/10/01</u> S (Fill in names of reviewers) Date:
Workers are encouraged to provide for the sign of the second seco	feedback on ES&H concerns or on ideal time fills out this section to Start Work: (Work germit has by Signature	een reviewed, work controls are in place Life wired NoYes Life #: Life #:	ce, and site is ready for job.) # 17500 Date 10/10/01 If (Fill in names of reviewers) Date: Date: Date:
Workers are encouraged to provide f 5. Work Requester or desig Conditions are Appropriate Name P. KROW 6. Work Requester determine Post Job Review: Name: Name: 7. Worker provides feedback Worker Feedback: 8. Work Control Coordinate	feedback on ES&H concerns or on ideal time fills out this section to Start Work: (Work permit has by Signature	een reviewed, work controls are in pla Life uired Life #: Life #: Life #: Juile #:	cce, and site is ready for job.) # 17500 Date 10/10/0/ s (Fill in names of reviewers) Date: Date: it and closes out
Workers are encouraged to provide f 5. Work Requester or desig Conditions are Appropriate Name P. KROW 6. Work Requester determine Post Job Review: Name: Name: 7. Worker provides feedback Worker Feedback: 8. Work Control Coordinate	feedback on ES&H concerns or on ideal time fills out this section to Start Work: (Work germit has by Signature	een reviewed, work controls are in pla Life uired Life #: Life #: Life #: Juile #:	cce, and site is ready for job.) # 17500 Date 10/10/0/ s (Fill in names of reviewers) Date: Date: it and closes out



Building 911 P.O. Box 5000 Upton, NY 11973-5000 Phone 516 344-4932 Fax 516 344-5954 makdisi@bnl.gov

managed by Brookhaven Science Associates for the U.S. Department of Energy

lemo

date:

October 9, 2001

to:

Derek Lowenstein

from:

Yousef Makdisi (on behalf of the Experiment Safety Review Committee)

subject:

Recommendation for approval to install the steel shielding inside the MuID

hole.

The PHENIX detector proposes to install a 6 inch thick shield liner on the inside of the MuID south square hole. The liner involves the base and two side walls.

- · An installation plan including engineering drawings was submitted and reviewed by Pearson and Makdisi on Oct 8, 2001.
- A meeting was held by PHENIX on October 9, 2001 to detail the plan to the primary
- A list of "responsible persons" who will supervise the job was also submitted.
- An escort policy is in effect for the duration of the work in the tunnel.
- The DX magnetic fringe field was measured by Cirnigliaro and Etkin on October 9, 2001. Less than 100 gauss and slow gradient.
- CAS watch will be notified of the work.
- A work plan will be signed prior to commencing the work on October 10, 2001.
- Safety shoes as well as leather gloves will be worn by all those involved in the installation.

I request approval for installation of the MuID south shield walls. All relevant documentation is in the C-AD Experiment Safety Review Committee files.

cc:

E. O'Brien

P. Kroon

C. Pearson

P. Pile

Approved: 10/9/01

File

Part B: Field Strength Measurement Record

	,	ON THE SKETCH (GRID) BELOW. EQUIVALENT METHODS (ECONOMICA (ECONOMICALE)
DISTANCE FROM SOURCE	LOCATION	READING	COMMENTS
	88_		COMMENTS

Sketch of Survey Area. (Indicate positions on map where measurements were	made \
	1, Pe + 10.4 30" > 0.4 0.3 213 12
T24	
Fait	×
(B)	itcr1
(Do.3)	
(0.2)	
Measuremen's INIMT	
0.1 mT = 1.0 Gauss	1
Symmetrical Magnet - Inside of Art egoluple	12 + tie.)

Forward the original form to the Static Magnetic Fields Subject Matter Expert, copies to your ES&H Coordinator and Facility Support Representative. Retain a copy in your files. Update and resubmit the assessment when changes occur.

FILE CODE: 1495SR. FORM 14-SMF (v1.0)

MuID Shielding Installation Plan - REVC.

The idea is to cover the floor and sides of the opening with 6 inches of steel. The z-coverage is 63 inches, enough to overlap the MuID steel for gaps 2 and 5 by ~ 1+ inch. The walls are built in two vertical sections, 24 inches wide and 39 inches wide, with the 24 inch section on the south end for independent removal to make it possible to regain access to the interior. Floor and walls are made up of stacked "bricks", 1/2 inch thick.

Six different size bricks are used, 3 for the floor and 2 for the walls and 1 for both. The quantities, sizes and weights are:

Q	Size - in	Wt. Lb.	
24	12x27	49	
48	6x36	33	
64	6x30	27	
36	6x18	17	
192	6x15	14	
336	6x24	22	

Before any plates are put in the opening, some unistrut has to be removed from the north end where it overhangs gap #2 where the shielding wall goes. A few tapped holes will be needed to support unistrut extensions over gap #5 on the east wall. Also, all the bolts in the existing floor plate except the four corners get removed, and some of the MuID electronics gets covered by plastic sheet. We also plan a 2-inch extension of the existing aluminum floor plate to avoid overhanging the edge with the steel plates.

The entire cavity will be checked again to make sure wires are as out of the way as possible. Everyone should be aware that the ion pump high voltage will remain on during this period.

The plates can be carried in and staged on the concrete sill by size while the opening is being prepared. I have arranged the size listing above to correspond to the order of use, i.e. the 12x27 are first, then 6x36 etc.

Drawings will be posted showing what goes where, and we may have to improvise a little on the floor to get around the ion pump extensions that weren't on the drawing, but we have a few spare 6x24's that can be used. The 24 heaviest pieces go on the floor beside the ion pump and are the first ones to go in. All the 6x24 and 6x15 are used on the walls, so they can go into the tunnel after the other sizes.

After the floor is finished, we will put up vertical unistruts to support the walls, and lay 8-inch channel on the floor as a base for the walls. The walls come next, starting with the west wall, north end, up to 36 inches. Bent sheet steel "clips" will be used periodically (every 16 inches?) to tie the wall to the unistrut as it rises. At some point (where needed, maybe at 24 inches?) another channel is planned to re-establish a reasonable base for the

rest of the wall, if it is needed. The south end of the west wall goes next in the same manner. Then the final 12 inches of the north end is completed using 6x30 and 6x15 bricks. This leaves the south end of the wall short to miss the vacuum valve.

After the west wall, the north end of the east wall gets built to full height of 48 inches above the floor. The south end of the east wall is last, and probably needs to be built completely from outside. This section is made up entirely of 6x24 inch bricks.

The trial wall was stacked Friday using 96 of the 6x24 bricks to the full height of 48 inches. This represents about 1/6 of the two walls (by number of bricks). We only used two clips, one about halfway up and one at the top. No surprises. In general the bricks are very flat and stackable, though some of them have a noticeable crown. The worst of these should be saved for the tops, and all of these should be stacked crown up to maximize stability.

Pete

GUIDELINES

No Accidents

Don't work tired, don't rush – we have plenty of time and help.

Wear safety shoes, but don't expect them to protect your feet

No heroics – this is not a contest or a race.

At least one blue card holder must be in the tunnel for every ten workers

At least on of the "responsible persons" must be there at all times work is going on. (Marino, LaBounty, Shea, Biggs, Cianciolo, Kroon)

The run shift leader must be kept up to date on tunnel activities.

STEPS

Restricted access starts at 0800 Wed AM.

Outside Cavity

Start "bucket brigade" to get plates into tunnel and stacked by size on the sill. Continue until all plates are in. – Organizer -

Inside Cavity

Cover sensitive MuID parts with plastic sheet - Atsushi

Remove MuID panel restraints attached to aluminum floor plate – Atsushi

Remove all other bolts in floor except four corners - Atsushi or Sal

Remove two vertical unistruts from north end and cut off 4 horizontal ends – Sal/Jim

Check cavity for wires and anything else sensitive or in the way - Sal

Drill and tap two 3/8-16 holes in southeast MuID steel plate to anchor extensions to existing horizontal unistruts (top and second one up from bottom) – Jim

Start Floor stack with 12x27 plates to east and west of ion pump – must leave 1 cm or more between pump and bricks

Complete floor per layouts

Install vertical unistrut supports – two for each of four wall sections, located by available space on horizontal unistruts. May save southeast two for later to keep entrance open.

Install unistrut spacers

Install 64-inch channel at base of each wall, clipped to unistruts.

Stack northwest wall section (39 inches in "z") up to 18 inches. The first course should start centered E-W in the channel (about one inch inside channel extremity).

Attach 39 inch Z-clip to unistruts and stack the next 18 inches.

Attach another 39-inch Z-clip to unistrut.

Stack southwest wall in same manner using the 24-inch Z-clips—stop before exceeding height of northwest section and before hitting vacuum valve.

Complete the northwest section to 48 inches above floor and cap with Z-clip.


Stack complete northeast wall section in same manner.


Clean up in side of cavity and stack last section from outside, using same scheme.


COMMENTS

At each Z-clip level, check for flatness of wall as base for rest. One channel section is available to place on top of the z-clip if it would provide a better base.


Spacers are provided up most of the vertical unistruts so the plates can be stacked against them to help keep everything aligned. However there are significant gaps for clips where it's up to the stacker to keep things lined up. N-S alignment is also important since each wall is in two sections.







EAST WALL VIEW LOOKING EAST



WEST WALL VIEW LOOKING WEST

